ISO 18646-6:2026-05 (E)

Robotics - Performance criteria and related test methods for service robots - Part 6: Lower-limb wearable robots

Contents

Page

Foreword ..... **iv**

1 Scope **1**

2 Normative references **1**

3 Terms and definitions **1**

4 Test conditions **2**
4.1 General 2
4.2 Wearable robot conditions 2
4.3 Environmental conditions 3
4.4 Operating conditions 3

5 Test device **3**
5.1 ATDR configuration requirements 3
5.2 ATDR size 4
5.3 ATDR signal measurement conditions 6
5.4 Safety considerations for the test setup 6

6 Preparation for the test **6**
6.1 Reference trajectory for ATDR walking 6
6.1.1 Configuration of the ATDR reference trajectory 6
6.1.2 Design of ATDR walking reference trajectory 7
6.2 ATDR half squat reference trajectory 8
6.2.1 Configuration of the ATDR reference trajectory 8
6.2.2 Design of ATDR half squat reference trajectory 9
6.3 ATDR control performance requirements 10
6.4 Wearable robot performance evaluation index 11
6.5 Ground reaction conditions 13

7 Test methods for walking test **13**
7.1 General 13
7.2 Test device 13
7.3 Test procedure 14
7.3.1 Test principle 14
7.3.2 No-load walking test 16
7.3.3 Loaded walking test 18

8 Test methods for half squat test **18**
8.1 General 18
8.2 Test device 18
8.3 Test procedure 19
8.3.1 Test principle 19
8.3.2 No-load half squat test 20
8.3.3 Loaded half squat test 21

9 Test report **21**

Bibliography **24**