ISO 27893:2026-07 (E)

Vacuum technology - Vacuum gauges - Evaluation of the uncertainties of results of calibrations by direct comparison with a reference gauge

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Symbols and abbreviated terms 3

5 Basic concept and model 3
5.1 General 3
5.2 Sum model 4
5.3 Quotient model 4
5.4 Combination of the two models 5

6 Calculation of uncertainty in the sum model 5
6.1 Total uncertainty -- Sum model 5
6.2 Uncertainty contributions due to reference standard 5
6.3 Uncertainty contributions due to unit under calibration 7
6.4 Uncertainty contributions due to calibration method or calibration conditions 8
6.5 Coverage factor 8

7 Calculation of uncertainty in the quotient model 8
7.1 Total uncertainty -- Quotient model 8
7.2 Uncertainty contributions due to reference standard 9
7.3 Uncertainty contributions due to the unit under calibration 10
7.4 Uncertainty contributions due to calibration method or calibration conditions 11
7.5 Coverage factor 12

8 Combination of the sum and quotient model for error of reading 12

9 Reporting uncertainties 13
9.1 Uncertainty budget 13
9.2 Calibration certificate 14

Annex A (normative) Efficient uncertainty analysis when Type A uncertainties are not negligible ... 15

Bibliography 17