DIN 6868-161:2013-01 (E)

Image quality assurance in diagnostic X-ray departments - Part 161: RöV acceptance testing of de ntal radiographic equipment for digital cone-beam computed tomography

Contents

Page

Foreword 4

1 Scope 6

2 Normative references 6

3 Terms and definitions 6

4 Performance of the ACCEPTANCE TEST 7
4.1 General 7
4.2 TEST PHANTOM 8
4.3 Test items 10
4.3.1 Visual inspection and functional tests 10
4.3.2 Alignment of the RADIATION FIELD and the active detector area 11
4.3.3 Reproducibility of the dose 11
4.3.4 Spatial resolution of the reconstruction 11
4.3.5 Spatial resolution 12
4.3.6 ACCEPTANCE INDEX 12
4.3.7 HOMOGENEITY INDEX 14
4.3.8 ARTEFACTS 15

Annex A (normative) Simplified determination of the MODULATION TRANSFER BEHAVIOUR 16

Annex B (normative) Calculation of the CONTRAST-TO-NOISE INDEX 18

Annex C (informative) Possible ARTEFACTS in DENTAL DIGITAL CONE-BEAM COMPUTED TOMOGRAPHY (CBCT) 20

C.1 General 20
C.2 Beam-hardening ARTEFACTS 20
C.3 Extinction ARTEFACTS 21
C.4 Partial volume effect and exponential-edge-gradient effect (EEGE) 22
C.5 Aliasing ARTEFACTS 22
C.6 Ring ARTEFACTS 23
C.7 ARTEFACTS caused by geometrical errors (e.g., motion ARTEFACTS) 24

Annex D (informative) Dose measurement in DENTAL DIGITAL CONE-BEAM COMPUTED TOMOGRAPHY (CBCT) -- Differences from computed tomography 25

D.1 Background 25
D.2 Prerequisites for the measurement of dose in DENTAL CBCT 25
D.2.1 Imaged volume 25
D.2.2 Scan geometry 25
D.2.3 Measurement devices 26
D.3 Summary 26

Annex E (informative) Figures 27

E.1 MODULATION TRANSFER BEHAVIOUR 28

E.2 Scan geometry 28
E.3 HOMOGENEITY 29

Bibliography 30

Keyword index 32

Figures Figure 1 -- Set-up and alignment of the TEST PHANTOM in the beam path 8

Figure 2 -- Homogeneous elements of the TEST PHANTOM 9

Figure 3 -- Structure elements of the TEST PHANTOM; top view and cross-sectional view 10

Figure C.1 -- Typical striped beam-hardening ARTEFACTS in the direction of the beam path, caused by metal implants (titanium) in DENTAL CBCT 21

Figure C.2 -- Extinction ARTEFACTS in the direction of the beam path due to very dense gold restorations in the teeth 21

Figure C.3 -- Intensity errors 22

Figure C.4 -- Subtle line patterns (Moiré patterns) 23

Figure C.5 -- Ring ARTEFACTS 23

Figure C.6 -- Typical motion ARTEFACTS that manifest themselves as double contours 24

Figure E.1 -- Example of the positioning and borders of the region of interest (ROI) used to determine the MODULATION TRANSFER BEHAVIOUR 27

Figure E.2 -- Example of the graphical presentation of the MODULATION TRANSFER BEHAVIOUR . 28

Figure E.3 -- Horizontal slice through a scan geometry (Example 1) 28

Figure E.4 -- Horizontal slice through a scan geometry (Example 2) 29

Figure E.5 -- Example for the position and borders of the fields for the determination of HOMOGENEITY 29