ISO 22127:2019-12 (E)

Dosimetry with radiophotoluminescent glass dosimete rs for dosimetry audit in MV X-ray radiotherapy

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Rules for the RPLD handling/reading procedure 5
4.1 Principle of measurement 5
4.2 Objective quantity of measurement 6
4.3 Handling of RPLDs 6
4.3.1 General remarks 6
4.3.2 Cleaning of RPLD element 6
4.4 Annealing 6
4.5 Irradiation of RPLD 6
4.5.1 Effective centre of measurement 6
4.5.2 Irradiation dose 6
4.6 Pre-heating 6
4.7 RPLD Reading 7
4.7.1 General remarks 7
4.7.2 Positioning RPLD elements on the reading tray 7
4.7.3 Determination of the RPL reading 7
4.7.4 Reader stability compensation by reference RPLDs 7

5 Evaluation of absorbed dose to water 7
5.1 Basic formula for the determination of absorbed dose to water 7
5.2 Mean readings of raw data 8
5.3 Evaluation of background element 8
5.4 Individual dosimeter sensitivity correction factor of each element 8
5.5 Calibration coefficient with reference RPLD element 8
5.6 Correction factor for individual reading tray position dependence 9
5.7 Correction factor for the radiation quality 9
5.8 Correction factor for phantom material 10
5.9 Correction factor for nonlinearity 10
5.10 Uncertainty of measurement of the absorbed dose 11

6 Requirements for the RPLD system 11
6.1 General information 11
6.2 Recommendations concerning completeness of the RPLD system 11
6.2.1 Technical components 11
6.2.2 Hardware and software components 12
6.2.3 Operating instructions 12
6.3 Requirements for RPLD detectors 13
6.3.1 Characteristics of RPLD materials 13
6.4 Requirements for RPLD-indicating instruments 14
6.4.1 General remarks 14
6.4.2 Mechanical construction and setup 14
6.4.3 Repeatable reading ability 14

6.4.4 Indication and indication range 14
6.4.5 Internal calibration glass 14
6.4.6 Operational failure and detection 14
6.4.7 Data output and data backup 15
6.5 Requirements for auxiliary instruments (pre-irradiation annealing and pre-heat devices) . 15
6.5.1 Pre-irradiation annealing 15
6.5.2 Pre-heat 15

6.5.3 Operation safety 15
6.5.4 Detection of function failure 15
6.5.5 Indication of the operating state 15

Bibliography 16