DIN EN ISO 15011-2:2010-03 (E)

Health and safety in welding and allied processes - Laboratory method for sampling fume and gases - Part 2: Determination of the emission rates of carbon monoxide (CO), carbon dioxide (CO<(Index)2>), nitrogen monoxid e (NO) and nitrogen dioxide (NO<(Index)2>) during arc welding, cutting and gouging (ISO 15011-2:2009)

Contents

Page

Foreword 3

Introduction 4

1 Scope 5

2 Normative references 5

3 Terms and definitions 5

4 Principle 6

5 Equipment and materials 6

6 Test procedures 8
6.1 Welding procedure selection 8
6.2 Setting up the test equipment 8
6.3 Blank test 9
6.4 Manual metal arc welding 9
6.5 Continuous wire processes and autogeneous TIG welding 9
6.6 Cutting and gouging 10

7 Calculating and reporting the results 11

Annex A (informative) Possible designs of hood 12

Annex B (informative) Equipment notes 14

Annex C (informative) Welding parameters for gas-shielded arc welding 16

Annex D (normative) Test procedures 19

Annex E (normative) Calculation of the average stable gas concentration 20

Annex F (normative) Test report 21

Bibliography 22