DIN EN ISO 15011-1:2010-03 (E)

Health and safety in welding and allied processes - Laboratory method for sampling fume and gases - Part 1: Determination of fume emission rate during arc welding and collection of fume for analysis (ISO 15011-1:2009)

Contents

Page

Foreword 3

Introduction 4

1 Scope 5

2 Normative references 5

3 Terms and definitions 5

4 Principle 6

5 Equipment and materials 6

6 Tests procedures 7
6.1 Welding procedure selection 7
6.2 Manual metal arc welding 7
6.3 Continuous wire processes 9
6.4 Analysis of the fume collected 11

7 Calculating and reporting the results 11

Annex A (informative) Possible designs of test chamber 12

Annex B (informative) Equipment notes 18

Annex C (informative) Welding parameters 20

Annex D (normative) Test procedures 22

Annex E (normative) Test report 23

Bibliography 24