ISO 15011-3:2009-10 (E)

Health and safety in welding and allied processes - Laboratory method for sampling fume and gases - Part 3: Determination of ozone emission rate during arc welding

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Principle 2

5 Equipment and materials 2

6 Tests procedures 4
6.1 Welding procedure selection 4
6.2 Setting up the test equipment 4
6.3 Trial tests 5
6.4 Emission rate testing 5

7 Calculating and reporting the results 6

Annex A (informative) Equipment notes 7

Annex B (informative) Welding parameters for ozone emission rate testing 9

Annex C (normative) Test procedures 11

Annex D (normative) Calculation of the average stable ozone concentration 12

Annex E (normative) Test report 13

Bibliography 14