ISO 15011-1:2009-10 (E)

Health and safety in welding and allied processe s - Laboratory method for sampling fume and gases - Part 1: Determination of fume emission rate during arc welding and collection of fume for analysis

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Principle 2

5 Equipment and materials 2

6 Tests procedures 3
6.1 Welding procedure selection 3
6.2 Manual metal arc welding 3
6.3 Continuous wire processes 5
6.4 Analysis of the fume collected 7

7 Calculating and reporting the results 7

Annex A (informative) Possible designs of test chamber 8

Annex B (informative) Equipment notes 14

Annex C (informative) Welding parameters 16

Annex D (normative) Test procedures 18

Annex E (normative) Test report 19

Bibliography 20