ISO 18592:2009-12 (E)

Resistance welding - Destructive testing of welds - Method for the fatigue testing of multi-spot-welded specimens

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 2

3 Terms and definitions 3

4 Symbols and abbreviated terms 5

5 Specimens 7
5.1 General 7
5.2 Selection of suitable specimens 8
5.3 Specimen fabrication 10
5.4 Specimen geometry 11

6 Requirements for testing machine 21

7 Specimen grips and alignment 22
7.1 General 22
7.2 Shear and peel loading 23

8 Test procedure 24
8.1 General 24
8.2 Mounting the H-specimens 24
8.3 Clamping procedure for the H-specimens 24
8.4 Fatigue test 24
8.5 Test termination 25

9 Test report 27
9.1 Basic information 27
9.2 Presentation of fatigue test results 28

Annex A (informative) Calibration specimen for verifying the load distribution in H-specimens 30

Annex B (informative) Hydraulic grips for the fatigue testing of H-specimens 31

Annex C (informative) Grip for the fatigue testing of H-specimens 32

Annex D (informative) Flow chart -- Data acquisition 33

Bibliography 36