DIN EN ISO 10882-1:2012-01 (E)

Health and safety in welding and alli ed processes - Sampling of airborne particles and gases in the operator's breathing zone - Part 1: Sampling of airborne particles (ISO 10882-1:2011)

Contents

Page

Foreword 3

Introduction 4

1 Scope 5

2 Normative references 5

3 Terms and definitions 6
3.1 General definitions 6
3.2 Sampling definitions 7
3.3 Welding terms 9
3.4 Statistical terms 11

4 Principle 12

5 Requirement 13

6 Equipment 13
6.1 Sampling equipment 13
6.2 Weighing equipment, if required 14

7 Assessment strategy 15

8 Measurement strategy 15
8.1 General 15
8.2 Personal exposure measurement 15
8.3 Fixed-point measurements 15
8.4 Selection of measurement conditions and measurement pattern 16

9 Procedure 17
9.1 Preliminary considerations 17
9.2 Preparation for sampling 18
9.3 Sampling position 19
9.4 Sampling 19
9.5 Transportation 20
9.6 Analysis 20
9.7 Expression of results 21

10 Exposure assessment 22

11 Recording of sampling data and presentation of results 22

Annex A (normative) Gravimetric analysis 23

Annex B (informative) Examples of arrangements for mounting samplers behind welder's face shields 25

Annex C (informative) An example of a report 32

Annex D (informative) Blank report form 35

Bibliography 38