ISO 10882-1:2011-10 (E)

Health and safety in welding and allied processes - Sampling of airborne particles and gases in the operator's breathing zone - Part 1: Sampling of airborne particles

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 2
3.1 General definitions 2
3.2 Sampling definitions 3
3.3 Welding terms 5
3.4 Statistical terms 7

4 Principle 8

5 Requirement 9

6 Equipment 9
6.1 Sampling equipment 9
6.2 Weighing equipment, if required 10

7 Assessment strategy 11

8 Measurement strategy 11
8.1 General 11
8.2 Personal exposure measurement 11
8.3 Fixed-point measurements 11
8.4 Selection of measurement conditions and measurement pattern 12

9 Procedure 13
9.1 Preliminary considerations 13
9.2 Preparation for sampling 14
9.3 Sampling position 15
9.4 Sampling 15
9.5 Transportation 16
9.6 Analysis 16
9.7 Expression of results 17

10 Exposure assessment 18

11 Recording of sampling data and presentation of results 18

Annex A (normative) Gravimetric analysis 19

Annex B (informative) Examples of arrangements for mounting samplers behind welder's face shields 21

Annex C (informative) An example of a report 28

Annex D (informative) Blank report form 31

Bibliography 34