ISO 15618-1:2016-09 (E)

Qualification testing of welders for underwater welding - Part 1: Hyperbaric wet welding

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Terms and definitions 2

4 Symbols and abbreviations 2
4.1 General 2
4.2 Test piece 2
4.3 Filler materials and fluxes 3
4.4 Miscellaneous 3

5 Essential variables for qualification testing 3
5.1 General 3
5.2 Welding processes 3
5.3 Joint types (butt and fillet welds) 4
5.4 Material groups 4
5.5 Filler materials and fluxes 4
5.6 Dimensions 4
5.7 Welding positions 5
5.8 Hyperbaric environment 5
5.9 Visibility 5

6 Range of qualification 5
6.1 General 5
6.2 Welding process 5
6.3 Joint types 6
6.4 Material groups 6
6.5 Filler materials 7
6.6 Dimensions 7
6.7 Welding positions 7
6.8 Hyperbaric environment 7

7 Examination and testing 9
7.1 General 9
7.2 Witnessing 9
7.3 Shapes and dimensions of test pieces 9
7.4 Welder-diver qualification test criteria 11
7.5 Test methods 11
7.6 Test pieces and test specimens 12
7.6.1 General 12
7.6.2 Butt welds in plate and pipe 12
7.6.3 Fillet welds on plate and pipe 13
7.7 Test report 15

8 Acceptance requirements for test pieces 15

9 Re-tests 15
10 Period and confirmation of validity 15
11 Revalidation of welder-diver qualification 16
12 Welder-diver qualification test certificate 16
13 Designation 16
Annex A (informative) Welder-diver qualification test certificate for hyperbaric wet welding 18
Annex B (informative) Job knowledge 20
Bibliography 23