ISO 5171:2019 (E)

Gas welding equipment — Pressure gauges used in welding, cutting and allied processes

Contents

Foreword

1 Scope

2 Normative references

3 Terms and definitions

4 Pressure

4.1 Unit of pressure
4.2 Maximum scale reading
4.3 Maximum pressure mark

5 Manufacturing requirements

5.1 Materials
5.1.1 General
5.1.2 Oxygen pressure gauges
5.2 Design and dimensions
5.2.1 Operational equipment
5.2.1.1 Accuracy
5.2.1.2 Overpressure and leakage test requirements
5.2.1.2.1 General
5.2.1.2.2 Test A
5.2.1.2.3 Test B
5.2.1.3 Torsion
5.2.1.4 Bending
5.2.1.5 Case vent test
5.2.2 Dimensions
5.2.3 Dial and pointer

6 Safety

7 Marking

8 Tests

8.1 General
8.2 Accuracy
8.3 Torsion test
8.4 Bend test
8.5 Case vent test
8.6 Overpressure and leakage test
8.6.1 Test A
8.6.2 Test B
8.7 Flammability test

Page count: 15