ISO 9455-17:2024-01 (E)

Soft soldering fluxes - Test methods - Part 17: Surface insulation resistance comb test and electrochemical migration test of flux residues

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Principle 1

5 Reagents 2

6 Apparatus 2

7 Inspection of test coupons 8
7.1 Surface plating 8
7.1.1 Slivering (thin metal overhang on etch runs) 8
7.1.2 Plating nodules 9
7.1.3 Plating pits 9
7.2 Surface laminate 9

8 Sample preparation 9
8.1 Preparation of the flux test solution 9
8.1.1 Liquid flux samples 9
8.1.2 Solid flux samples 9
8.1.3 Flux-cored solder wire or preform samples 9
8.1.4 Solder paste samples 10
8.1.5 Paste flux samples 10
8.2 Preparation of the test coupons 10
8.2.1 Sample identification 10
8.2.2 Test coupons 10
8.2.3 Test coupon pre-cleaning 11

9 Procedure 11
9.1 Methods for connecting test coupons 11
9.1.1 Board circuitry layout 11
9.1.2 Preconditioning of SIR test coupons prior to processing (optional) 13
9.2 Fluxing and soldering test patterns 13
9.2.1 Liquid and solid flux samples and flux-cored solder wire samples 13
9.2.2 Soldering using wave solder system 13
9.2.3 Soldering using static solder pot 13
9.2.4 Solder paste samples 14
9.2.5 Paste flux samples 14
9.3 Cleaning 14
9.4 SIR measurement 15
9.4.1 High-resistance measurement system verification 15
9.4.2 Test coupon measurements 15
9.5 Electrochemical migration test 15

10 Assessment 16

11 Precision 16

12 Test report 16

Annex A (informative) SIR testing guidance 18

Annex B (informative) Surface insulation resistance comb test and electrochemical migration test of flux residues -- Qualification test report 20

Bibliography 22