ISO 10882-2:2000-09 (E)

Health and safety in welding and allied processes_- Sampling of airborne particles and gases in the operator's breathing zone_- Part_2: Sampling of gases

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 2

3 Terms and definitions 2

4 Description of measurement methods 6

4.1 General 6

4.2 Direct reading electrical apparatus 7

4.3 Detector tubes 7

4.4 Indirect methods involving laboratory analysis 8

5 Requirements 9

6 Assessment strategy 9

7 Measurement strategy 10

7.1 General 10

7.2 Personal exposure measurements 10

7.3 Fixed point measurements 10

7.4 Selection of measurement conditions and measurement pattern 10

8 Sampling 11

8.1 Sampling position 11

8.2 Sampling equipment 11

8.3 Sample filtration 12

8.4 Multiple sampling 12

8.5 Volume of sampling line 12

8.6 Flow rate 12

8.7 Handling of temperature, pressure and humidity data 12

9 Measurement of individual gases and vapours 13

9.1 General 13

9.2 Ozone (0,01 ppm to 3 ppm) 13

9.3 Carbon monoxide (3 ppm to 500 ppm) 13

9.4 Carbon dioxide (500 ppm to 10 %) 14

9.5 Nitric oxide (1 ppm to 100 ppm) and nitrogen dioxide (0,3 ppm to 250 ppm) 14

9.6 Vapours 15

10 Recording of test data and presentation of results 16

Annex A (Informative) Measurement of individual gases and vapours 17

Annex B (informative) An example of a test report 18

B.1 Basic data 18

B.2 Process data 19

B.3 Sampling data and test results 20

Bibliography 21