ISO/TR 22824:2024-12 (E)

Welding - Best practices for specification and measurement of ferrite in stainless steel weld metal

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Metallurgical phenomena of ferrite in stainless steel weld metal 2
4.1 General 2
4.2 Solidification mode 3
4.2.1 General 3
4.2.2 A solidification mode (austenitic) 3
4.2.3 AF solidification mode (primary austenite) 3
4.2.4 FA solidification mode (primary ferrite) 3
4.2.5 F solidification mode (ferritic) 4
4.2.6 Mixed solidification modes 4
4.3 Solid state phase transformation of ferrite to austenite 5
4.3.1 General 5
4.3.2 A solidification mode alloys 6
4.3.3 AF solidification mode alloys 6
4.3.4 FA solidification mode alloys 6
4.3.5 F solidification mode alloys 7
4.4 Constitution diagrams 7
4.5 Effects of welding conditions on ferrite 11
4.5.1 General 11
4.5.2 Welding conditions which affect chemical composition 12
4.5.3 Welding conditions which don't affect chemical composition 13
4.6 Alpha prime and intermetallic phase formation 13
4.7 Chromium nitrides and secondary austenite 14
4.8 Postweld heat treatment 14

5 Effects of ferrite variations on service performance of stainless steel weld metal 15
5.1 General 15
5.2 Tensile properties at ambient temperatures 16
5.3 Toughness 16
5.4 Resistance to chloride stress corrosion cracking (CSCC) 16
5.5 Susceptibility to corrosion in certain media 17
5.6 Creep resistance 17

6 Measurement of ferrite in stainless steel weld metal 18
6.1 General 18
6.2 Considerations in ferrite measurement 19
6.3 Metallographic percent ferrite by optical methods 19
6.4 Metallographic measurement of ferrite by EBSD 20
6.5 Ferrite measurement by x-ray diffraction 20
6.6 Ferrite measurement by electrochemical dissolution of austenite 20
6.7 Ferrite measurement by saturation magnetization 20
6.8 Ferrite measurement by magnetic attraction 20

6.9 Measurement by magnetic permeability (magnetic induction) 21
6.10 Location and volume of measurement 22
6.11 Measurement in the HAZ 23
6.12 Reproducibility of measurement 23
6.13 Correlations between Ferrite Number and ferrite percent 23

7 Specification of ferrite in stainless steel weld metal 24
7.1 General 24
7.2 Non-magnetic requirements 25
7.3 Service environments in which ferrite is aggressively attacked 25
7.4 Cryogenic applications requiring weld metal toughness 25
7.5 High temperature service 26
7.6 Dissimilar welds 26
7.7 Buffer layers and cladding 26
7.8 Duplex ferritic-austenitic welds 27

8 Outliers in ferrite measurement 27

9 Conclusions 28

Bibliography 30