ISO/TS 8182:2026-08 (E)

Welding and allied processes - Requirements and recommendations for the use of the welding parameters related to the arc energy for qualification and specification of welding procedures

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Symbols and abbreviated terms 2

5 Risk levels 3

6 Measuring welding parameters during WPQR welding 3
6.1 Calibration, validation of the measuring equipment 3
6.2 Determination of runs to be measured 4
6.3 Length of run in pipe and plate 4
6.4 Weaving width in relation with arc energy 4
6.5 Arc voltage, welding current, length of the run, welding speed, arc energy and temperature 4
6.5.1 General 4
6.5.2 Arc voltage (U) 5
6.5.3 Welding current (I) 5
6.5.4 Length of the run 5
6.5.5 Welding speed 5
6.5.6 Arc energy 5
6.5.7 Preheat temperature 5
6.5.8 Interpass temperature 5

7 Reporting welding variables to a WPQR 5

8 Transferring WPQR welding parameters to a WPS 6
8.1 Welding areas 6
8.2 Thickness 6
8.3 Arc-voltage, welding current and welding speed in relation to arc energy 7
8.4 Relation preheat- and interpass temperature and arc energy 7
8.5 Weaving width in relation with arc energy 7

9 Measuring welding parameters during production welding 7
9.1 Calibration, validation of the measuring equipment 7
9.2 Determination of several weld areas 7
9.2.1 Length of the run in pipe and plate 8
9.3 Weaving width in relation with arc energy 8
9.4 Preheat temperature 8
9.5 Interpass temperature 8

Annex A (informative) Example WPQR sheet for a weld divided in several weld areas 9

Annex B (informative) Example sheet WPS with alternative calculation of arc energy based on Annex A and the applicable risk level 10

Bibliography 11