ISO/TR 17844:2004-09 (E)

Welding - Comparison of standardised methods for the avoidance of cold cracks

Contents

Page

Foreword vi

Introduction vii

1 Scope 1

2 CE-method 1
2.1 Cracking test method 1
2.2 Parent metal composition range 1
2.3 Plate thickness and joint geometry 2
2.4 Hydrogen level and welding process 2
2.4.1 Hydrogen scales 2
2.4.2 Selection of hydrogen scales 2
2.5 Heat input 3
2.6 Special considerations 7
2.6.1 Conditions which might require more stringent procedures 7
2.6.2 Relaxations 8
2.6.3 Simplified conditions for manual metal-arc welding 8
2.7 Determination of preheat 10

3 CET-method 18
3.1 Cracking test method 18
3.2 Parent metal composition range 19
3.3 Plate thickness 20
3.4 Hydrogen level and welding process 21
3.5 Heat input 21
3.6 Influence of residual stress 22
3.7 Determination of preheat 22
3.7.1 Calculation of the minimum preheat temperature 22
3.7.2 Example for determination : numerical determination of the preheat temperature 23
3.7.3 Example for determination : graphical determination of the preheat temperature 23
3.8 Special considerations 25
3.8.1 Reduction of hydrogen content by post heating (soaking) 25
3.8.2 Welding with reduced preheating 25
3.8.3 Welding with austenitic consumables 25

4 CEN-method 25
4.1 Cracking test method 25
4.2 Parent metal composition range 26
4.3 Material thickness 27
4.4 Weld metal hydrogen content and welding process 27
4.5 Heat input 27
4.6 Weld metal yield strength 28
4.7 Determination of preheat 29
4.8 Special considerations 29
4.8.1 Weld metal hydrogen content 29
4.8.2 Number of the weld layers and weld metal strength 30
4.8.3 Restraint 30
4.8.4 Weld metal hydrogen cracking 30

5 Pcm-method 34
5.1 General 34

5.1.1 Cracking test method 34
5.1.2 HAZ hardness control method 34
5.1.3 Hydrogen controlled method 35
5.2 Parent metal composition range 35
5.2.1 Hardness controlled method 35
5.2.2 Hydrogen controlled method 35
5.2.3 Selection of method 35
5.2.4 Hydrogen controlled method 36
5.3 Plate thickness and joint geometry 36
5.3.1 HAZ hardness controlled method 36
5.3.2 Hydrogen controlled method 36
5.4 Hydrogen levels and welding process 37
5.4.1 HAZ hardness controlled method 37
5.4.2 Hydrogen controlled method 37
5.5 Energy input 37
5.6 Special considerations 38
5.7 Determination of minimum preheat 38
5.7.1 Method according to value of CE 38
5.7.2 HAZ hardness controlled method 38
5.7.3 Hydrogen content controlled method 39

Annex A (informative) Comparison of the different methods 48

A.1 General 48
A.2 Parent metal composition range 48
A.3 Plate thickness and joint geometry 48
A.4 Hydrogen levels 49
A.5 Heat input 49
A.6 Prediction comparison 49
A.7 Summary and conclusions 50

Annex B (informative) Abbreviations 71

Bibliography 72