ISO 21438-2:2009-12 (E)

Workplace atmospheres - Determination of inorganic acids by ion chromatography - Part 2: Volatile acids, except hydrofluoric acid (hydrochloric acid, hydrobromic acid and nitric acid)

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Terms and definitions 2
3.1 General definitions 2
3.2 Particle size fraction definitions 3
3.3 Sampling definitions 4
3.4 Analytical definitions 4
3.5 Statistical terms 5

4 Principle 6

5 Requirement 7

6 Reagents 7

7 Apparatus 9
7.1 Sampling equipment 9
7.2 Laboratory apparatus 11

8 Occupational exposure assessment 13
8.1 General 13
8.2 Personal sampling 13
8.3 Static sampling 13
8.4 Selection of measurement conditions and measurement pattern 13

9 Sampling 14
9.1 Preliminary considerations 14
9.2 Preparation for sampling 16
9.3 Sampling position 17
9.4 Collection of samples 17
9.5 Transportation 17

10 Analysis 18
10.1 Preparation of test and calibration solutions 18
10.2 Instrumental analysis 19
10.3 Estimation of detection and quantification limits 20
10.4 Quality control 20
10.5 Measurement uncertainty 21
11 Expression of results 22
12 Method performance 22
12.1 Sampling efficiency and sample storage 22
12.2 Quantification limits 22
12.3 Upper limits of the working range 22

12.4 Bias and precision 23
12.5 Uncertainty of sampling and analysis method 23
12.6 Interferences 23
13 Test report 23
13.1 Test record 23
13.2 Laboratory report 24

Annex A (informative) Temperature and pressure correction 25

Annex B (normative) Filter materials 27

Bibliography 28