ISO 15202-1:2012-06 (E)

Workplace air - Determination of metals and metalloids in airborne particulate matter by inductively coupled plasma atomic emission spectrometry - Part 1: Sampling

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1
3.1 Generaldefinitions 2
3.2 Particlesizefractiondefinitions 3
3.3 Samplingdefinitions 4

4 Principle 4

5 Requirement 4

6 Sampling equipment 5
6.1 Samplers 5
6.2 Filters 5
6.3 Sampling pumps 5
6.4 Flowmeter 6
6.5 Ancillary equipment 6

7 Occupational exposure assessment 7
7.1 General 7
7.2 Personal sampling 7
7.3 Static sampling 7
7.4 Selection of measurement conditions and measurement pattern 7

8 Sampling method 8
8.1 Preliminary considerations 8
8.2 Preparation for sampling 9
8.3 Sampling position 10
8.4 Collection of samples 11
8.5 Transportation 11

9 Documentation 11
9.1 Sampling information 11
9.2 Information to accompany the request for analytical services 12

Annex A (informative) Sampler wall deposits 13

Annex B (informative)Guidanceonfilterselection 15

Annex C (informative)Temperatureandpressurecorrectionfortheindicatedvolumetricflowrate 17

Bibliography 18