ISO 20581:2016-11 (E)

Workplace air - General requirements for the performance of procedures for the measurement of chemical agents

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 2

4 Classification 2
4.1 General 2
4.2 Screening measurements of time-weighted average concentration 2
4.3 Screening measurements of variation of concentration in time and/or space 2
4.4 Measurements for comparison with occupational exposure limit values 2
4.5 Periodic measurements 2

5 Performance requirements 3
5.1 General 3
5.2 Screening measurements of time-weighted average concentration 3
5.3 Screening measurements of variation of concentration in time and/or space 3
5.4 Measurements for comparison with limit values and periodic measurements 3
5.4.1 Unambiguity 3
5.4.2 Selectivity 3
5.4.3 Averaging time 4
5.4.4 Measuring range 4
5.4.5 Expanded uncertainty 4
5.4.6 Chemical agents where compliant methods are not available 4
5.5 Composite procedures 4
5.6 Transport, handling and/or storage 5
5.7 Environmental conditions 5
5.8 Description of measuring procedure 5
5.9 Dimension of result 5
5.10 Additional requirements 5

6 Test method 6

7 Validation report 7

Annex A (informative) Structure of a method description 8

Annex B (informative) Calculation of uncertainty of measurement 9

Bibliography 16