DIN EN 15051-3:2026-01 (E)

Workplace exposure - Measurement of the dustiness of bulk materials - Part 3: Continuous drop method

Contents

Page

European foreword 3

Introduction 4

1 Scope 5

2 Normative references 5

3 Terms and definitions 6

4 Requirements 6
4.1 General 6
4.2 Conditioning of the bulk material 6
4.2.1 As-received condition 6
4.2.2 Conditioning specifications 6
4.3 Sample and environmental control 6
4.4 Moisture content 6
4.5 Bulk density 7
4.6 Test procedure 7
4.7 Replicate tests 7
4.8 In-house / test powder 7
4.9 Reporting 7

5 Continuous drop method 7
5.1 Description of test apparatus 7
5.2 Filters 9
5.3 Ancillary equipment 9
5.4 Preparation of test sample 9
5.5 Preparation of test apparatus 10
5.6 Test procedure 10
5.7 Weighing the filters 10
5.8 Limit of detection (LOD) and limit of quantification (LOQ) 11
5.9 Determination of the inhalable and respirable dustiness mass fractions 12

6 Evaluation of dustiness 13

7 Test report 13

Bibliography 15