ISO 16740:2005-02 (E)

Workplace air - Determination of hexavalent chromium in airbor ne particulate matter - Method by ion chromatography and spectrophotometric measurement using diphenyl carbazide

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Terms and definitions 2
3.1 General definitions 2
3.2 Particle size fraction definitions 3
3.3 Sampling definitions 3
3.4 Analytical definitions 4
3.5 Statistical terms 5

4 Principle 6

5 Reactions 7

6 Requirement 7

7 Reagents 7

8 Apparatus 10
8.1 Sampling equipment 10
8.2 Laboratory apparatus 12

9 Occupational exposure assessment 15
9.1 General 15
9.2 Personal sampling 15
9.3 Static sampling 16
9.4 Selection of measurement conditions and measurement pattern 16

10 Sampling method 17
10.1 Preliminary considerations 17
10.2 Preparation for sampling 18
10.3 Sampling position 19
10.4 Collection of samples 19
10.5 Transportation 20

11 Analysis 21
11.1 Analytical requirements 21
11.2 Preparation of solutions for determination of soluble hexavalent chromium compounds 22
11.3 Preparation of solutions for determination of insoluble hexavalent chromium compounds 23
11.4 Instrumental analysis 25
11.5 Estimation of detection and quantification limits 27
11.6 Quality control 27
11.7 Measurement uncertainty 28

12 Expression of results 28

13 Method performance 29
13.1 Sample collection and stability 29
13.2 Hotplate extraction 29
13.3 Ultrasonic extraction 29
13.4 Interferences 29

14 Special cases 30
14.1 Spray-painting 30
14.2 Action to be taken when particles have become dislodged from the filter during transportation 30

15 Test report 30
15.1 Test record 30
15.2 Laboratory report 31

Annex A (informative) Temperature and pressure corrections 32

Annex B (informative) Background on methods for determination of hexavalent chromium in air and guidance on their use 34

Bibliography 38