ISO 9951:1993-12 (E)

Measurement of glas flow in closed conduits; turbine meters

Contents

Page

1 Scope 1

2 Normative references 1

3 Definitions and symbols 1
3.1 Definitions 1
3.2 Symbols and subscripts 2

4 Principle of the method of measurement 3

5 Flowrates 3

6 Meter construction 3
6.1 General 3
6.2 Materials 3
6.3 Shell 3
6.4 Connections and maximum flowrates 3
6.5 Length 3
6.6 Pressure tappings 3
6.7 Flow direction 4
6.8 Meter having a removable meter mechanism 4
6.9 Overloading 4
6.10 Marking 4

7 Pressure testing 4
7.1 General 4
7.2 Test fluid 4
7.3 Strength test of the pressure-containing parts
7.4 Meter leakage test 5

8 Performance characteristics 5
8.1 Error 5
8.2 Calibration 5
8.3 Meter position 5
8.4 Temperature range 5
8.5 Pressure loss 5
8.6 Installation conditions 6
8.7 Mechanically driven external equipment 6

9 Output and readout 6
9.1 General 6
9.2 Counters 6
9.3 Flowrate Output 6
9.4 Mechanical Output 6
9.5 Voltage-free contact 6
9.6 Electrical pulse output 6
9.7 Electrical safety 6

Annexes

A Recommendations for use 7

B Other meter Performance characteristics 9

C Data computation and presentation **10**

D Field checks **11**

E Perturbations **12**