ISO 29864:2018 (E)

Self adhesive tapes — Measurement of breaking strength and elongation at break

Contents

Foreword

Introduction

1 Scope

2 Normative references

3 Terms and definitions

4 Significance and use

5 Principle

6 Apparatus

- 6.1 Tensile testing machine
- 6.2 Clamps
- 6.3 Cylinders
- 6.4 Scale
- 6.5 Cutting tool

7 Test sample and test pieces

8 Procedure

- 8.1 Testing conditions
- 8.2 Preparation of test pieces
- 8.3 Method A for non-filament tapes
- 8.4 Method B for filament tapes

9 Expression of results

- 9.1 Expression of results for non-filament tapes
- 9.2 Expression of results for filament tapes

10 Test report

Page count: 6