DIN 55508-5:2021-04 (E)

Packaging test - Leakage test on flexible packagings - Part 5: Water bath method (bubble test)

Contents

Page

Foreword ... 3

1 Scope ... 4

2 Normative references ... 4

3 Terms and definitions ... 4

4 Test method ... 5
4.1 General ... 5
4.2 Water bath method using negative pressure ... 5
4.2.1 Characterization of method ... 5
4.2.2 Special advantages of the method ... 6
4.2.3 Restrictions ... 6
4.2.4 Devices and equipment — Leakage testing device ... 6
4.2.5 Test objects and sampling ... 7
4.2.6 Procedure ... 7
4.2.7 Evaluation ... 7
4.2.8 Test report ... 7
4.3 Water bath method using positive pressure ... 8
4.3.1 Characterization of method ... 8
4.3.2 Special advantages of the method ... 8
4.3.3 Restrictions ... 8
4.3.4 Sealing the gas supply on the flexible packaging ... 8
4.3.5 Connection point ... 9
4.3.6 Test pressure ... 9
4.3.7 Devices and equipment — Leakage testing device ... 9
4.3.8 Test objects and sampling ... 9
4.3.9 Procedure ... 10
4.3.10 Evaluation ... 10
4.3.11 Test report ... 10

Bibliography ... 11

Figures

Figure 1 — Schematic representation of the water bath method using negative pressure ... 6
Figure 2 — Schematic representation of the water bath method using positive pressure ... 8