ISO 3547-7:2020-05 (E)

Plain bearings - Wrapped bushes - Part 7: Measurement of wall thickness of thin-walled bushes

Contents

Page

Foreword ..... **iv**

1 Scope **1**

2 Normative references **1**

3 Terms and definitions **1**

4 Symbols and units **2**

5 Purpose of checking **2**

6 Checking methods **2**

6.1 Measuring principle 2

6.2 Line measurement around the circumference 3

6.3 Point measurement 4

7 Requirements for measuring equipment for the contact method **4**

7.1 Radius of the measuring pin on the outside surface 4

7.2 Radius of the measuring pin on the inside surface 5

7.3 Measuring pin load 5

8 Checking of measuring equipment **5**

Bibliography **6**