ISO 3548-2:2020 (E)

Plain bearings — Thin-walled half bearings with or without flange — Part 2: Measurement of wall thickness and flange thickness

Contents

Foreword

1 Scope

2 Normative references

3 Terms and definition

4 Symbols and units

5 Purpose of checking

6 Checking methods

- 6.1 Measuring principle of wall thickness
- 6.2 Line measurement around the circumference
- 6.3 Line measurement in axial direction
- 6.4 Point measurement
- 6.5 Grading of bearings
- 6.6 Eccentric bore
- 6.7 Measuring principle for flange thickness
- 6.8 Measuring point for flange thickness

7 Requirements for measuring equipment and specimen for the contact method

- 7.1 Tip-radius for measuring pin on the outside surface
- 7.2 Tip-radius for measuring pin on the inside surface
- 7.3 Measuring pin load
- 7.4 Set-up
- 7.5 Periodical control
- 7.6 Measurement failures on the inside and/or outside surface

8 Checking of measuring equipment

Page count: 10