DIN 66399-2:2012-10 (E)

Office machines - Destruction of data carriers - Part 2: Requirements for equipment for destruction of data carriers

Contents

Page

Foreword 3

1 Scope 4

2 Normative references 4

3 Terms and definitions 4

4 Requirements 4
4.1 Degree of destruction 4
4.2 Materials referred to in security levels 4
4.3 Limits for particle sizes 4
4.4 Feed and collection apparatus 12
4.5 Checking that destruction is complete 12

5 Testing 12
5.1 Ambient conditions 12
5.2 Test material 12
5.3 Testing the rated throughput 13
5.4 Testing the degree of destruction 13
5.4.1 Purpose of the test 13
5.4.2 Feeding in the test material 13
5.4.3 Sample quantity 13
5.4.4 Sampling from destroyed test material 13
5.4.5 Analysis 13
5.4.6 Evaluation 14

6 Test report 14

7 Test certificate 15

Tables Table 1 -- Information in the original size 6

Table 2 -- Information in miniaturized form 7

Table 3 -- Information on optical data carriers 8

Table 4 -- Information on magnetic data carriers 9

Table 5 -- Information on hard drives with magnetic data carriers 10

Table 6 -- Information on electronic data carriers 11