ISO/IEC 15426-2:2005-03 (E)

Information technology - Automatic identification and data capture techniques - Bar code verif ier conformance specification - Part 2: Two-dimensional symbols

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Conformance 1

3 Normative references 2

4 Terms and definitions 2

5 Symbols 2

6 Functional requirements 2
6.1 General requirements 2
6.2 Reflectance calibration 3
6.3 Mandatory functions 3
6.3.1 Verifiers for multi-row bar code symbols 3
6.3.2 Verifiers for two-dimensional matrix symbols 3
6.4 Optional functions 4

7 General constructional and operational requirements 4
7.1 Installation, operation and maintenance 4
7.2 Power supply 4
7.3 Temperature 4
7.3.1 Operating temperature range 4
7.3.2 Storage temperature range 4
7.4 Humidity 4
7.5 Ambient light immunity 5

8 Test requirements 5
8.1 Test methods 5
8.1.1 Selection of equipment for testing 5
8.1.2 Scanning parameters 5
8.1.3 Test measurements 5
8.2 Test environment 5
8.3 Primary reference test symbols 5
8.4 Test report 6

9 Certification and labelling 7

10 Equipment specification 7

Annex A (normative) Primary reference test symbols 8

Annex B (normative) Verification requirements for primary reference test symbols 13