DIN EN 16602-70-08:2015-05 (E)

Space product assurance - Manual soldering of high-reliability electrical connections; English version EN 16602-70-08:2015

Foreword **9**

Introduction **10**

1 Scope **11**

2 Normative references **12**

3 Terms, definitions and abbreviated terms **13**

3.1 Terms from other standards 13

3.2 Terms specific to the present standard 13

3.3 Abbreviated terms 20

4 Principles of reliable soldered connections **22**

5 Preparatory conditions **23**

5.1 Calibration 23

5.2 Facility cleanliness 23

5.3 Environmental conditions 23

5.4 Lighting requirements 24

5.5 Precautions against static discharges 24

5.5.1 General 24

5.5.2 Precautions against ESD during manufacturing 24

5.5.3 Protective Packaging and ESD Protection 25

5.5.4 Packing and filler materials 26

5.6 Equipment and tools 26

5.6.1 General 26

5.6.2 Brushes 26

5.6.3 Cutters and pliers 26

5.6.4 Bending tools 27

5.6.5 Clinching tools 27

5.6.6 Insulation strippers 28

5.6.7 Soldering irons and resistance soldering equipment 29

5.6.8 Soldering tools 30

6 Materials selection 31
6.1 General 31
6.2 Solder 31
6.2.1 Form 31
6.2.2 Composition 31
6.3 Flux 32
6.3.1 Rosin-based fluxes 32
6.3.2 INH1 corrosive acid flux 33
6.3.3 Application of flux 33
6.4 Solvents 34
6.5 Flexible insulation materials 34
6.6 Terminals 35
6.6.1 Materials 35
6.6.2 Tin-, silver- and gold-plated terminals 35
6.6.3 Shape of terminals 35
6.7 Wires 35
6.8 PCBs 36
6.8.1 Boards 36
6.8.2 Gold finish on conductors 36
6.9 Component lead finishes 36
6.10 Adhesives (staking compounds and heat sinking), encapsulants and conformal coatings 36

7 Preparation for soldering 38
7.1 General 38
7.1.1 Tools 38
7.1.2 Components 38
7.2 Preparation of conductors, terminals and solder cups 38
7.2.1 Insulation removal 38
7.2.2 Surfaces to be soldered 39
7.2.3 De-golding of gold-plated leads and terminals 40
7.2.4 Constraints on degolding and pretinning methods 41
7.2.5 Pretinning of stranded wires 42
7.2.6 Pre-tinning of component leads and solid-wire conductors 42
7.3 Preparation of the soldering bit 43
7.3.1 Fit 43
7.3.2 Maintenance 43
7.3.3 Plated bits 43

7.3.4 Tip in operation 43
7.4 Maintenance of resistance-type soldering electrodes....44
7.5 Handling (work station)....44
7.6 Storage (work station)....44
7.6.1 Components....44
7.6.2 PCBs....44
7.6.3 Materials requiring segregation 44
7.7 Preparation of PCBs for soldering....45
7.7.1 Process....45
7.7.2 Demoisturization methods....45
7.7.3 Storage of prepared PCBs 45
8 Mounting of components....46
8.1 General requirements....46
8.1.1 Introduction 46
8.1.2 Heavy components 46
8.1.3 Metal-case components 46
8.1.4 Glass-encased components....47
8.1.5 Stress relief of components with bendable leads....47
8.1.6 Stress relief of components with non-bendable leads....48
8.1.7 Reinforced plated-through holes 50
8.1.8 Lead and conductor cutting....50
8.1.9 Solid hook-up wire....50
8.1.10 Location 50
8.1.11 Conformal coating, cementing and encapsulation 50
8.2 Lead bending requirements 51
8.2.1 General....51
8.2.2 Conductors terminating on both sides of a non-plated-through hole....51
8.3 Mounting of terminals to PCBs....52
8.4 Lead attachment to PCBs....53
8.4.1 General....53
8.4.2 Clinched leads 53
8.4.3 Stud leads....55
8.4.4 Lapped round leads 56
8.4.5 Lapped ribbon leads....56
8.5 Mounting of components to terminals 56
8.6 Mounting of connectors to PCBs....58
9 Attachment of conductors to terminals, solder cups and cables 59

9.1 General....59
9.1.1 Conductors....59
9.1.2 Terminals....59
9.2 Wire termination....59
9.2.1 Breakouts from cables....59
9.2.2 Insulation clearance....59
9.2.3 Solid hook-up wire....60
9.2.4 Stress relief....60
9.3 Turret and straight-pin terminals....60
9.3.1 Side route....60
9.3.2 Bottom route....60
9.4 Bifurcated terminals....61
9.4.1 General....61
9.4.2 Bottom route....61
9.4.3 Side route....62
9.4.4 Top route....63
9.4.5 Combination of top and bottom routes....64
9.4.6 Combination of side and bottom routes....64
9.5 Hook terminals....64
9.6 Pierced terminals....65
9.7 Solder cups (connector type)....66
9.8 Insulation sleeving....66
9.9 Wire and cable interconnections....67
9.9.1 General....67
9.9.2 Preparation of wires....67
9.9.3 Preparation of shielded wires and cables....67
9.9.4 Pre-assembly....68
9.9.5 Soldering procedures....68
9.9.6 Cleaning....69
9.9.7 Inspection....69
9.9.8 Workmanship....69
9.9.9 Sleeving of interconnections....69
9.10 Connection of stranded wires to PCBs....70

10 Soldering to terminals and PCBs....72

10.1 General....72
10.1.1 Securing conductors....72
10.1.2 Thermal shunts....72

10.1.3 High-voltage connections 72
10.2 Solder application to terminals 73
10.2.1 Soldering of swaged terminals onto PCBs 73
10.2.2 Soldering of conductors onto terminals (except cup terminals) 73
10.2.3 Soldering of conductors onto cup terminals 74
10.3 Solder application to PCBs 74
10.3.1 Solder coverage 74
10.3.2 Solder fillets 74
10.3.3 Soldering of component leads to plated-through holes 74
10.3.4 Solder application 75
10.4 Wicking 76
10.5 Solder rework 76
10.6 Repair and modification 76
11 Cleaning of PCB assemblies 77
11.1 General 77
11.2 Ultrasonic cleaning 77
11.3 Monitoring for cleanliness 77
11.3.1 Cleanliness testing 77
11.3.2 Testing frequency 78
11.3.3 Test limits 78
11.3.4 Test method 78
12 Final inspection 79
12.1 General 79
12.2 Acceptance criteria 79
12.3 Visual rejection criteria 80
13 Verification procedure 81
13.1 General 81
13.2 Vibration 81
13.3 Temperature cycling 84
13.4 Microsection 84
14 Quality assurance 85
14.1 General 85
14.2 Data 85
14.3 Nonconformance 85
14.4 Calibration 85
14.5 Traceability 86

14.6 Workmanship standards 86
14.7 Inspection 86
14.8 Operator and inspector training and certification 86

15 Workmanship standards 88
15.1 Soldered clinched terminals 88
15.2 Soldered stud terminals 89
15.3 Soldered turret terminals 90
15.4 Solder turret terminals 91
15.5 Soldered bifurcated terminals 92
15.6 Soldered hook terminals 93
15.7 Soldered cup terminals 94
15.8 Soldered wire to shielded cable interconnections 95

Annex A (normative) Report on manual soldering of high-reliability electrical connections - DRD 98

Annex B (informative) Solder melting temperatures and choice 102

Bibliography 103

Figures

Figure 5-1: Profiles of correct and incorrect cutters for trimming leads 27
Figure 5-2 Examples of non-approved types of mechanical strippers 28
Figure 8-1: Assembly of underfilled TO-39 and TO-59, and adhesively staked CKR06 48
Figure 8-2: Methods for incorporating stress relief with components having bendable leads 49
Figure 8-3: Methods for attaching wire extensions to non-bendable leads 50
Figure 8-4: Minimum lead bend 51
Figure 8-5: Leads with solder termination on both sides 52
Figure 8-6: Types of terminal swaging 53
Figure 8-7: Clinched-lead terminations - unsupported holes 54
Figure 8-8: Clinched lead terminations - plated through-holes 54
Figure 8-9: Stud terminations 55
Figure 8-10: Methods of through-hole lapped termination 57
Figure 8-11: Method of stress relieving parts attached to terminals 57
Figure 9-1: Side- and bottom-route connections to turret terminals 61
Figure 9-2: Bottom-route connections to bifurcated terminal 62
Figure 9-3: Side-route connection to bifurcated terminal 63
Figure 9-4: Top-route connection to bifurcated terminal 64

Figure 9-5: Connections to hook terminals 65
Figure 9-6: Connections to pierced terminals 65
Figure 9-7: Connections to solder cups (connector type)....66
Figure 9-8: Methods for securing wires....69
Figure 9-9: Connection of stranded wires to PCBs 71
Figure 10-1: High voltage connection 73
Figure 10-2:Minimum acceptable wetting on component side....75
Figure 15-1:Soldered clinched terminals 88
Figure 15-2: Soldered stud terminals....89
Figure 15-3: Soldered turret terminals with twin conductors 90
Figure 15-4: Soldered turret terminals with single conductors....91
Figure 15-5: Soldered bifurcated terminals....92
Figure 15-6 Soldered hook terminals....93
Figure 15-7: Soldered cup terminals....94
Figure 15-8: Hand-soldered wire to shielded cable interconnections 95
Figure 15-9: Hand-soldered wire to shielded wire interconnections 96
Figure 15-10: Hand-soldered wire interconnections - details of defects 97

Tables

Table 6-1: Chemical composition of spacecraft solders....32
Table 6-2: Fluxes....33
Table 7-1: Clearances for insulation 39
Table 7-2: Solder baths for degolding and pretinning 41
Table 9-1: Dimensions for Figure 9-9 71
Table 13-1: Sine survey....82
Table 13-2: Minimum severity for sine vibration testing 83
Table 13-3: Minimum severity for random vibration testing for all applications except launchers 83
Table 13-4: Minimum severity for random vibration testing for launcher 83

Table B-1 : Guide to choice of solder types 102