DIN EN 16602-70-08:2015-05 (E)

Space product assurance - Manual soldering of high-reliability electrical connections; English version EN 16602-70-08:2015

Foreword 9

Introduction 10

1 Scope 11

2 Normative references 12

3 Terms, definitions and abbreviated terms 13

3.1 Terms from other standards 13

3.2 Terms specific to the present standard 13

3.3 Abbreviated terms 20

4 Principles of reliable soldered connections 22

5 Preparatory conditions 23

5.1 Calibration 23

5.2 Facility cleanliness 23

5.3 Environmental conditions 23

5.4 Lighting requirements 24

5.5 Precautions against static discharges 24

5.5.1 General 24

5.5.2 Precautions against ESD during manufacturing 24

5.5.3 Protective Packaging and ESD Protection 25

5.5.4 Packing and filler materials 26

5.6 Equipment and tools 26

5.6.1 General 26

5.6.2 Brushes 26

5.6.3 Cutters and pliers 26

5.6.4 Bending tools 27

5.6.5 Clinching tools 27

5.6.6 Insulation strippers 28

5.6.7 Soldering irons and resistance soldering equipment 29

5.6.8 Soldering tools 30

6 Materials selection 31
6.1 General..31
6.2 Solder 31
  6.2.1 Form 31
  6.2.2 Composition 31
6.3 Flux 32
  6.3.1 Rosin-based fluxes..32
  6.3.2 INH1 corrosive acid flux 33
  6.3.3 Application of flux 33
6.4 Solvents...34
6.5 Flexible insulation materials...34
6.6 Terminals...35
  6.6.1 Materials 35
  6.6.2 Tin-, silver- and gold-plated terminals..35
  6.6.3 Shape of terminals 35
6.7 Wires 35
6.8 PCBs 36
  6.8.1 Boards 36
  6.8.2 Gold finish on conductors...36
6.9 Component lead finishes 36
6.10 Adhesives (staking compounds and heat sinking), encapsulants and conformal coatings...36

7 Preparation for soldering...38
7.1 General..38
  7.1.1 Tools..38
  7.1.2 Components...38
7.2 Preparation of conductors, terminals and solder cups...............................38
  7.2.1 Insulation removal..38
  7.2.2 Surfaces to be soldered 39
  7.2.3 De-golding of gold-plated leads and terminals.......................................40
  7.2.4 Constraints on degolding and pretinning methods.................................41
  7.2.5 Pretinning of stranded wires...42
  7.2.6 Pre-tinning of component leads and solid-wire conductors....................42
7.3 Preparation of the soldering bit 43
  7.3.1 Fit...43
  7.3.2 Maintenance 43
  7.3.3 Plated bits 43

7.3.4 Tip in operation 43
7.4 Maintenance of resistance-type soldering electrodes 44
7.5 Handling (work station) 44
7.6 Storage (work station) 44
7.6.1 Components 44
7.6.2 PCBs 44
7.6.3 Materials requiring segregation 44
7.7 Preparation of PCBs for soldering 45
7.7.1 Process 45
7.7.2 Demoisturization methods 45
7.7.3 Storage of prepared PCBs 45

8 Mounting of components 46

8.1 General requirements 46
8.1.1 Introduction 46
8.1.2 Heavy components 46
8.1.3 Metal-case components 46
8.1.4 Glass-encased components 47
8.1.5 Stress relief of components with bendable leads 47
8.1.6 Stress relief of components with non-bendable leads 48
8.1.7 Reinforced plated-through holes 50
8.1.8 Lead and conductor cutting 50
8.1.9 Solid hook-up wire 50
8.1.10 Location 50
8.1.11 Conformal coating, cementing and encapsulation 50
8.2 Lead bending requirements 51
8.2.1 General 51
8.2.2 Conductors terminating on both sides of a non-plated-through hole 51
8.3 Mounting of terminals to PCBs 52
8.4 Lead attachment to PCBs 53
8.4.1 General 53
8.4.2 Clinched leads 53
8.4.3 Stud leads 55
8.4.4 Lapped round leads 56
8.4.5 Lapped ribbon leads 56
8.5 Mounting of components to terminals 56
8.6 Mounting of connectors to PCBs 58

9 Attachment of conductors to terminals, solder cups and cables 59

9.1 General....59
    9.1.1 Conductors....59
    9.1.2 Terminals....59
9.2 Wire termination....59
    9.2.1 Breakouts from cables....59
    9.2.2 Insulation clearance....59
    9.2.3 Solid hook-up wire....60
    9.2.4 Stress relief....60
9.3 Turret and straight-pin terminals....60
    9.3.1 Side route....60
    9.3.2 Bottom route....60
9.4 Bifurcated terminals....61
    9.4.1 General....61
    9.4.2 Bottom route....61
    9.4.3 Side route....62
    9.4.4 Top route....63
    9.4.5 Combination of top and bottom routes....64
    9.4.6 Combination of side and bottom routes....64
9.5 Hook terminals....64
9.6 Pierced terminals....65
9.7 Solder cups (connector type)....66
9.8 Insulation sleeving....66
9.9 Wire and cable interconnections....67
    9.9.1 General....67
    9.9.2 Preparation of wires....67
    9.9.3 Preparation of shielded wires and cables....67
    9.9.4 Pre-assembly....68
    9.9.5 Soldering procedures....68
    9.9.6 Cleaning....69
    9.9.7 Inspection....69
    9.9.8 Workmanship....69
    9.9.9 Sleeving of interconnections....69
9.10 Connection of stranded wires to PCBs....70

10 Soldering to terminals and PCBs....72

10.1 General....72
    10.1.1 Securing conductors....72
    10.1.2 Thermal shunts....72

10.1.3 High-voltage connections 72
10.2 Solder application to terminals 73
10.2.1 Soldering of swaged terminals onto PCBs 73
10.2.2 Soldering of conductors onto terminals (except cup terminals) 73
10.2.3 Soldering of conductors onto cup terminals 74
10.3 Solder application to PCBs 74
10.3.1 Solder coverage 74
10.3.2 Solder fillets 74
10.3.3 Soldering of component leads to plated-through holes 74
10.3.4 Solder application 75
10.4 Wicking 76
10.5 Solder rework 76
10.6 Repair and modification 76

11 Cleaning of PCB assemblies 77
11.1 General 77
11.2 Ultrasonic cleaning 77
11.3 Monitoring for cleanliness 77
11.3.1 Cleanliness testing 77
11.3.2 Testing frequency 78
11.3.3 Test limits 78
11.3.4 Test method 78

12 Final inspection 79
12.1 General 79
12.2 Acceptance criteria 79
12.3 Visual rejection criteria 80

13 Verification procedure 81
13.1 General 81
13.2 Vibration 81
13.3 Temperature cycling 84
13.4 Microsection 84

14 Quality assurance 85
14.1 General 85
14.2 Data 85
14.3 Nonconformance 85
14.4 Calibration 85
14.5 Traceability 86

14.6 Workmanship standards 86
14.7 Inspection 86
14.8 Operator and inspector training and certification 86

15 Workmanship standards 88
15.1 Soldered clinched terminals 88
15.2 Soldered stud terminals 89
15.3 Soldered turret terminals 90
15.4 Solder turret terminals 91
15.5 Soldered bifurcated terminals 92
15.6 Soldered hook terminals 93
15.7 Soldered cup terminals 94
15.8 Soldered wire to shielded cable interconnections 95

Annex A (normative) Report on manual soldering of high-reliability electrical connections - DRD 98

Annex B (informative) Solder melting temperatures and choice 102

Bibliography 103

Figures

Figure 5-1: Profiles of correct and incorrect cutters for trimming leads 27
Figure 5-2 Examples of non-approved types of mechanical strippers 28
Figure 8-1: Assembly of underfilled TO-39 and TO-59, and adhesively staked CKR06 48
Figure 8-2: Methods for incorporating stress relief with components having bendable leads 49
Figure 8-3: Methods for attaching wire extensions to non-bendable leads 50
Figure 8-4: Minimum lead bend 51
Figure 8-5: Leads with solder termination on both sides 52
Figure 8-6: Types of terminal swaging 53
Figure 8-7: Clinched-lead terminations - unsupported holes 54
Figure 8-8: Clinched lead terminations - plated through-holes 54
Figure 8-9: Stud terminations 55
Figure 8-10: Methods of through-hole lapped termination 57
Figure 8-11: Method of stress relieving parts attached to terminals 57
Figure 9-1: Side- and bottom-route connections to turret terminals 61
Figure 9-2: Bottom-route connections to bifurcated terminal 62
Figure 9-3: Side-route connection to bifurcated terminal 63
Figure 9-4: Top-route connection to bifurcated terminal 64

Figure 9-5: Connections to hook terminals 65
Figure 9-6: Connections to pierced terminals 65
Figure 9-7: Connections to solder cups (connector type) 66
Figure 9-8: Methods for securing wires 69
Figure 9-9: Connection of stranded wires to PCBs 71
Figure 10-1: High voltage connection 73
Figure 10-2:Minimum acceptable wetting on component side 75
Figure 15-1:Soldered clinched terminals 88
Figure 15-2: Soldered stud terminals 89
Figure 15-3: Soldered turret terminals with twin conductors 90
Figure 15-4: Soldered turret terminals with single conductors 91
Figure 15-5: Soldered bifurcated terminals 92
Figure 15-6 Soldered hook terminals 93
Figure 15-7: Soldered cup terminals 94
Figure 15-8: Hand-soldered wire to shielded cable interconnections 95
Figure 15-9: Hand-soldered wire to shielded wire interconnections 96
Figure 15-10: Hand-soldered wire interconnections - details of defects 97

Tables

Table 6-1: Chemical composition of spacecraft solders 32
Table 6-2: Fluxes 33
Table 7-1: Clearances for insulation 39
Table 7-2: Solder baths for degolding and pretinning 41
Table 9-1: Dimensions for Figure 9-9 71
Table 13-1: Sine survey 82
Table 13-2: Minimum severity for sine vibration testing 83
Table 13-3: Minimum severity for random vibration testing for all applications except launchers 83
Table 13-4: Minimum severity for random vibration testing for launcher 83

Table B-1 : Guide to choice of solder types 102