DIN EN 16602-70-13:2015-05 (E)

Space product assurance - Measurements of the peel and pull-off strength of coatings and finishes using pressure-sensitive tapes; English version EN 16602-70-13:2015

Table of contents

Foreword **4**

1 Scope **5**

2 Normative references **6**

3 Terms, definitions and abbreviated terms **7**

3.1 Terms from other standards 7

3.2 Terms specific to the present standard 7

3.3 Abbreviated terms 7

4 Principles **8**

5 Requirements **10**

5.1 Preparatory conditions 10

5.1.1 Hazards, health and safety precautions 10

5.1.2 Preparation of samples 10

5.1.3 Facilities 12

5.1.4 Equipment 12

5.2 Test procedure 14

5.2.1 Preparation 14

5.2.2 Peel and pull-off test 14

5.2.3 Handling and packaging of tested samples 15

5.3 Acceptance criteria 15

5.4 Quality assurance 16

5.4.1 Data 16

5.4.2 Nonconformance 16

5.4.3 Calibration 16

5.4.4 Traceability 16

Annex A (normative) **Test result sheet - DRD** **17**

Annex B (informative) **Peel and pull-off test procedure** **20**

Annex C (informative) **Fracture lines** **22**

Bibliography.....23

Figures

Figure 4-1 Test procedure flow diagram 9

Figure 5-1: Side view of the test fixtures 13

Figure A-1 : Example of test result sheet 19

Figure C-1 : Schematic cross-section of a coated substrate showing various fracture lines dependent on the weakest layer 22