ISO 5858:2026-05 (E)

Aerospace - Nuts, self-locking, with maximum operating temperature less than or equal to 425 °C - Procurement specification

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Quality assurance 3
4.1 General 3
4.1.1 Manufacturer's approval 3
4.1.2 Qualification of nuts 3
4.1.3 Production acceptance of nuts 3
4.2 Qualification inspection and test conditions 3
4.3 Production acceptance inspection and test conditions 4
4.4 Use of statistical process control (SPC) 4

5 Technical requirements 5

Annex A (normative) Types of permissible surface discontinuity 28

Annex B (informative) Cross-sectional area formula 29

Bibliography 30