ISO/TS 25138:2010-12 (E)

Surface chemical analysis - Analysis of metal oxide films by glow-discharge optical-emission spectrometry

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Principle 1

4 Apparatus 2
4.1 Glow-discharge optical-emission spectrometer 2

5 Adjusting the glow-discharge spectrometer system settings 3
5.1 General 3
5.2 Setting the parameters of a DC source 4
5.3 Setting the discharge parameters of an RF source 5
5.4 Minimum performance requirements 6

6 Sampling 8

7 Calibration 8
7.1 General 8
7.2 Calibration specimens 8
7.3 Validation specimens 10
7.4 Determination of the sputtering rate of calibration and validation specimens 11
7.5 Emission intensity measurements of calibration specimens 12
7.6 Calculation of calibration equations 12
7.7 Validation of the calibration 12
7.8 Verification and drift correction 14

8 Analysis of test specimens 14
8.1 Adjusting discharge parameters 14
8.2 Setting of measuring time and data acquisition rate 14
8.3 Quantifying depth profiles of test specimens 15

9 Expression of results 15
9.1 Expression of quantitative depth profile 15
9.2 Determination of metal oxide mass per unit area 15
9.3 Determination of the average mass fractions of the elements in the oxide 16

10 Precision 16

11 Test report 17

Annex A (normative) Calculation of calibration constants and quantitative evaluation of depth profiles 18

Annex B (informative) Suggested spectral lines for determination of given elements 29

Annex C (informative) Examples of oxide density and the corresponding quantity O 30

Annex D (informative) Report on interlaboratory testing of metal oxide films 31

Bibliography 36