ISO 1352:2011-04 (E)

Metallic materials - Torque-controlled fatigue testing

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Symbols and abbreviated terms 3

5 Principle of test 3

6 Test plan 4

7 Shape and size of specimen 4
7.1 Form 4
7.2 Dimensions 5

8 Preparation of specimens 6
8.1 General 6
8.2 Machining procedure 6
8.3 Sampling and marking 6
8.4 Surface conditions of specimen 7
8.5 Dimensional checks 7
8.6 Storage and handling 7

9 Apparatus 7
9.1 Testing machine 7
9.2 Instrumentation for test monitoring 9

10 Test procedure 9
10.1 Mounting of specimen 9
10.2 Speed of testing 9
10.3 Application of torque 9
10.4 Calculation of nominal torsional stress 10
10.5 Recording of temperature and humidity 10
10.6 Failure and termination criteria 10

11 Test report 10

Annex A (informative) Presentation of results 14

Annex B (informative) Verification of alignment of torsional fatigue testing machines 18

Annex C (informative) Measuring uniformity of torsional strain (stress) state 20

Bibliography 23