ISO 28704:2011-08 (E)

Fine ceramics (advanced ceramics, advanced technical ceramics) - Test method for cyclic bending fatigue of porous ceramics at room t emperature

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Testing machine and equipment 3
4.1 Testing machine 3
4.2 Loading precision 3
4.3 Test fixture 4
4.4 Micrometer callipers for measurement of external dimensions 4
4.5 Dial gauge 4
4.6 Vernier callipers 4

5 Test piece 5
5.1 Test piece size 5
5.2 Test piece preparation 5

6 Test method 5
6.1 Waveform of loading stress 5
6.2 Loading method 5
6.3 Number of cycles for interruption 6
6.4 Reuse of test piece 6
6.5 Recommended test procedure in fatigue test 6
6.6 Test environment 6

7 Treatment of test result 6
7.1 Maximum stress 6
7.2 Number of cycles to failure 7
7.3 S-N plot 7

8 Test report 7