ISO 12111:2011-08 (E)

Metallic materials - Fatigue testing - Strain-controlled thermomechanical fatigue testing method

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Symbols 3

5 Apparatus 4
5.1 Testing machine 4
5.2 Strain measuring system 5
5.3 Heating system 5
5.4 Instrumentation for test monitoring 5
5.5 Checking and verification of the apparatus 6

6 Specimens 6
6.1 Geometry 6
6.2 Preparation of specimens 9
6.3 Machining procedure 10
6.4 Sampling and marking 10
6.5 Surface condition of the specimen 11
6.6 Dimensional check 11
6.7 Storage and handling of specimens 11

7 Procedure 12
7.1 Laboratory environment 12
7.2 Specimen mounting 12
7.3 Temperature control 12
7.4 Temperature gradients 12
7.5 Mechanical strain control 13
7.6 Thermal strain compensation 13
7.7 Temperature/mechanical strain phasing 15
7.8 Command waveforms 16
7.9 Start of test 16
7.10 Monitoring the test 17
7.11 Failure criteria 17
7.12 Failure 18
7.13 Test interruption sequence 18

8 Expression of results 18
8.1 Preliminary data 18
8.2 Reduction of recorded data 18
8.3 Analysis of results 18

9 Test report 19
9.1 Aim of the study 19
9.2 Material 19

9.3 Specimen 19
9.4 Test equipment details 19
9.5 Description of test methodology 19
9.6 Test termination technique including definition of failure 19
9.7 Deviations from specified test tolerances or recommended procedures 19
9.8 Test conditions 20
9.9 Presentation of results 20

Annex A (informative) Representative diagrams 21

Annex B (informative) Modulus of elasticity determination 24

Bibliography 25