ISO 14719:2011-12 (E)

Chemical analysis of refractory material glass and glazes - Determination of Fe<(hoch)2+> and Fe<(hoch)3+> by the spectra l photometric method with 1,10-phenanthroline

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Principle of Methods A and B 2

5 Sample preparation 2

6 Interferences 2

7 Sample disintegration and measurement 2

8 Calculation and expression of results 9

9 Test report 10

Annex A (informative) Precision 11

Bibliography 13