ISO 17636-2:2013-01 (E)

Non-destructive testing of welds - Radiographic testing - Part 2: X- and gamma-ray techniques with digital dete ctors

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 2

4 Symbols and terms 5

5 Classification of radiographic techniques 6

6 General 7
6.1 Protection against ionizing radiation 7
6.2 Surface preparation and stage of manufacture 7
6.3 Location of the weld in the radiograph 8
6.4 Identification of radiographs 8
6.5 Marking 8
6.6 Overlap of digital images 8
6.7 Types and positions of image quality indicators (IQI) 8
6.8 Minimum image quality values 9
6.9 Personnel qualification 10

7 Recommended techniques for making digital radiographs 10
7.1 Test arrangements 10
7.2 Choice of tube voltage and radiation source 16
7.3 Detector systems and metal screens 18
7.4 Alignment of beam 20
7.5 Reduction of scattered radiation 20
7.6 Source-to-object distance 22
7.7 Geometric magnification technique 25
7.8 Maximum area for a single exposure 26
7.9 Processing 26
7.10 Monitor viewing conditions and storage of digital radiographs 27

8 Examination report 28

Annex A (normative) Recommended number of exposures which give an acceptable examination of a circumferential butt weld 30

Annex B (normative) Minimum image quality values 35

Annex C (normative) Determination of basic spatial resolution 41

Annex D (normative) Determination of minimum grey values for CR practice 45

Annex E (informative) Grey values, general remarks 50

Bibliography 52