ISO 7539-11:2013-04 (E)

Corrosion of metals and alloys - Stress corrosion cracking - Part 11: Guidelines for testing the resistance of metals and alloys to hydrogen embrittlement and hydrogen-assisted cracking

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Factors to be considered in hydrogen embrittlement and hydrogen-assisted cracking testing 1
3.1 Dynamic plastic straining 1
3.2 Test time and hydrogen uptake 2
3.3 Temperature 2

4 Selection of test method 3
4.1 General 3
4.2 Specimen type 3
4.3 Test duration 3
4.4 Load form 8
4.5 Pre-charging and hydrogen effusivity 12
4.6 Testing of welds 12

5 Post-test evaluation 13

Bibliography 15