DIN EN ISO 13588:2013-11 (E)

Non-destructive testing of welds - Ultrasonic testing - Use of automated phased array technology (ISO 13588:20 12)

Contents

Page

Foreword 3

1 Scope 4

2 Normative references 4

3 Termsanddefinitions 5

4 Testing levels 5

5 Information required prior to testing 7
5.1 Itemstobedefinedpriortoproceduredevelopment 7
5.2 Specificinformationrequiredbytheoperatorbeforetesting 7
5.3 Written test procedure 7

6 Requirements for personnel and equipment 8
6.1 Personnelqualifications 8
6.2 Equipment 8

7 Preparation for testing 8
7.1 Volume to be inspected 8
7.2 Verificationoftestset-up 9
7.3 Scan increment setting 9
7.4 Geometry considerations 9
7.5 Preparation of scanning surfaces 9
7.6 Temperature 9
7.7 Couplant 9

8 Testing of base material 10

9 Range and sensitivity settings 10
9.1 Settings 10
9.2 Checking of the settings 11
9.3 Reference blocks 11

10 Equipment checks 12

11 Procedurequalification 12

12 Weld testing 12

13 Data storage 13

14 Interpretation and analysis of phased array data 13
14.1 General 13
14.2 Assessing the quality of the phased array data 13
14.3 Identificationofrelevantindications 13
14.4 Classificationofrelevantindications 13
14.5 Determination of location and length of an indication 14
14.6 Indication assessment 14
14.7 Evaluation against acceptance criteria 14

15 Test report 14

Annex A (informative)Typicalreferenceblocksandreferencereflectors 16

Bibliography 20