ISO 9513:1999-04 (E)

Metallic materials - Calibration of extensometers used in uniaxial testing

Contents

Page

1 Scope 1

2 Symbols and designations 1

3 Principle 2

4 Calibration apparatus 2

5 Procedure 2
5.1 Position of the extensometer 2
5.2 Temperature at which the calibration is made 2
5.3 Accuracy of gauge length of the extensometer 2
5.4 Range of calibration 3
5.5 Calibration procedure 3
5.6 Determination of the characteristics of the extensometer 3

6 Classification of the extensometer 3

7 Frequency of calibration 4

8 Calibration report 5

Annex A (informative) Example of calibration ranges of an extensometer 6

Annex B (informative) Parameters for classification of an extensometer 7

Bibliography 10