ISO 12135:2016-11 (E)

Metallic materials - Unified method of test for the determination of quasistatic fracture toughness

Contents

Page

Foreword v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Symbols and designations 2

5 General requirements 5
5.1 General 5
5.2 Fracture parameters 7
5.3 Fracture toughness symbols 8
5.4 Test specimens 8
5.4.1 Specimen configuration and size 8
5.4.2 Specimen preparation 12
5.5 Pre-test requirements 18
5.5.1 Pre-test measurements 18
5.5.2 Crack shape/length requirements 19
5.6 Test apparatus 19
5.6.1 Calibration 19
5.6.2 Force application 19
5.6.3 Displacement measurement 19
5.6.4 Test fixtures 20
5.7 Test requirements 24
5.7.1 Three-point bend testing 24
5.7.2 Compact tension testing 24
5.7.3 Specimen test temperature 24
5.7.4 Recording 25
5.7.5 Testing rates 25
5.7.6 Test analyses 25
5.8 Post-test crack measurements 25
5.8.1 General 25
5.8.2 Initial crack length, ao 25
5.8.3 Stable crack extension, a 28
5.8.4 Unstable crack extension 28

6 Determination of fracture toughness for stable and unstable crack extension 29
6.1 General 29
6.2 Determination of plane strain fracture toughness, Klc 30
6.2.1 General 30
6.2.2 Interpretation of the test record for FQ 30
6.2.3 Calculation of KQ 31
6.2.4 Qualification of KQ as Klc 32
6.3 Determination of fracture toughness in terms of 32
6.3.1 Determination of Fc and Vc, Fu and Vu, or Fuc and Vuc 32
6.3.2 Determination of Fm and Vm 34
6.3.3 Determination of Vp 34
6.3.4 Calculation of 34
6.3.5 Qualification of fracture toughness value 35

6.4 Determination of fracture toughness in terms of J 35
6.4.1 Determination of Fc and qc, Fu and qu, or Fuc and quc 35
6.4.2 Determination of Fm and qm 36
6.4.3 Determination of Up 36
6.4.4 Calculation of Jo 37
6.4.5 Qualification of Jo fracture toughness value 37

7 Determination of resistance curves J-a and J-a and initiation toughness J0,2BL and J0,2BL and Ji and Ji for stable crack extension 38

7.1 General 38
7.2 Test procedure 38
7.2.1 General 38
7.2.2 Multiple-specimen procedure 38
7.2.3 Single-specimen procedure 38
7.2.4 Final crack front straightness 38
7.3 Calculation of J and J 39
7.3.1 Calculation of J 39
7.3.2 Calculation of J 39
7.4 R-curve plot 40
7.4.1 Plot construction 41
7.4.2 Data spacing and curve fitting 42
7.5 Qualification of resistance curves 42
7.5.1 Qualification of J-a resistance curves 42
7.5.2 Qualification of J-a resistance curves 43
7.6 Determination and qualification of J0,2BL and J0,2BL 44
7.6.1 Determination of J0,2BL 44
7.6.2 Determination of J0,2BL 45
7.7 Determination of initiation toughness Ji and Ji by scanning electron microscopy (SEM) 46 8 Test report 46

8.1 Organization 46
8.2 Specimen, material and test environment 47
8.2.1 Specimen description 47
8.2.2 Specimen dimensions 47
8.2.3 Material description 47
8.2.4 Additional dimensions 47
8.2.5 Test environment 47
8.2.6 Fatigue precracking conditions 47
8.3 Test data qualification 48
8.3.1 Limitations 48
8.3.2 Crack length measurements 48
8.3.3 Fracture surface appearance 48
8.3.4 Pop-in 48
8.3.5 Resistance curves 48
8.3.6 Checklist for data qualification 48
8.4 Qualification of Klc 49
8.5 Qualification of the J-R Curve 49
8.6 Qualification of the J-R Curve 50
8.7 Qualification of J0,2BL(B) as J0,2BL 50
8.8 Qualification of J0,2BL(B) as J0,2BL 50

Annex A (informative) Determination of Ji and Ji 51

Annex B (normative) Crack plane orientation 56

Annex C (informative) Example test reports 57

Annex D (normative) Stress intensity factor coefficients and compliance relationships 66

Annex E (informative) Measurement of load-line displacement q in the three-point bend test 71

Annex F (informative) Derivation of pop-in formulae 76

Annex G (informative) Analytical methods for the determination of Vp and Up 78

Annex H (informative) Guidelines for single-specimen methods 80

Annex I (normative) Power-law fits to crack extension data (see Reference [42]) 95

Bibliography 96