DIN EN ISO 20486:2018-05 (E)

Non-destructive testing - Leak testing - Calibration of reference leaks for gases (ISO 20486:2017)

Contents

Page

European foreword ... **4**

Foreword ... **5**

1 Scope ... **6**

2 Normative references ... **7**

3 Terms and definitions ... **7**

4 Nominal leakage rates ... **8**

5 Classification of leaks ... **8**
5.1 Permeation leak ... 8
5.2 Conductance leaks ... 8
5.2.1 Capillary leak ... 8
5.2.2 Aperture leak (orifice) ... 9
5.2.3 Compressed powder leak ... 9

6 Calibration by comparison ... **9**
6.1 Methods A, A_S, B and B_S ... 9
6.2 Applicability of comparison methods ... 9
6.3 Preparation of leaks and apparatus ... 10
6.3.1 Leak detector ... 10
6.3.2 Connection to the leak detector ... 10
6.3.3 Temperature accommodation ... 12
6.4 Measurement ... 12
6.4.1 Set-up ... 12
6.4.2 General measurement sequence ... 12
6.5 Evaluation for methods A, A_S, B and B_S (Comparison) ... 13
6.5.1 Determination of leakage rate ... 13
6.5.2 Influence factors to measurement uncertainty ... 14

7 Volumetric calibration ... **15**
7.1 Direct flow (Method C) ... 15
7.1.1 General ... 15
7.1.2 Equipment ... 15
7.1.3 Preparation of leaks and apparatus ... 15
7.1.4 Measurement ... 16
7.1.5 Evaluation for Method C (direct flow measurement) ... 18
7.2 Leak measurement under water (Method D) ... 19
7.2.1 General ... 19
7.2.2 Equipment ... 19
7.2.3 Preparation of leaks and apparatus ... 19
7.2.4 Measurement ... 20
7.2.5 Evaluation for Method D ... 21
7.2.6 Influence factors to measurement uncertainty ... 22
7.3 Calibration by (volumetric) gas meter (Method E) ... 22
7.3.1 General ... 22
7.3.2 Equipment ... 23
7.3.3 Preparation of leaks and apparatus ... 23
7.3.4 Measurement ... 23
7.3.5 Evaluation for Method E (gas meter) ... 23
7.3.6 Influence factors to measurement uncertainty ... 24

7.4 Calibration by pressure change in a known volume (Method F) 24
7.4.1 General 24
7.4.2 Preparation of leaks and apparatus 25
7.4.3 Measurement 27
7.4.4 Special situation in vacuum chambers 28
7.4.5 Evaluation for Method F (pressure change) 30
7.4.6 Influence factors to measurement uncertainty 30
7.5 Calibration by volume change at constant pressure (Method G) 31
7.5.1 Equipment 31
7.5.2 Preparation of leaks and apparatus 31
7.5.3 Measurement 31
7.5.4 Evaluation for Method G (volume change at constant pressure) 32
8 General influences 33
9 Report 33
10 Labelling of reference leaks 34
11 Handling of reference leaks 34
11.1 General 34
11.2 Permeation leaks (normally with reservoir fitted the leak outlet) 34
11.3 Conductance leaks (normally without reservoir) 34
Annex A (informative) **Calculation of leakage rate decrease due to tracer gas depletion in the reservoir 35**
Bibliography 37