DIN 53015:2019-06 (E)

Viscometry - Measurement of viscosity using the Hoeppler Falling-Ball Viscometer

Contents

Page

Foreword 4

1 Scope 5

2 Normative references 5

3 Terms and definitions 5

4 Symbols and units 5

5 Measuring range 8

6 Principle 9

7 Theory behind method 9

8 Apparatus 9
8.1 Höppler falling-ball viscometer 9
8.2 Thermometer 11
8.3 Timer 11
8.4 Thermostat 11
8.5 Density measurement equipment 11

9 Sampling 11

10 Procedure 12
10.1 Sample preparation 12
10.2 Ball selection 12
10.3 Measuring the fall time 13
10.3.1 Preparation for measurement 13
10.3.2 Determining the fall time 13
10.3.3 Measuring the density of liquid 13
10.4 Evaluation 14
10.5 Test report 14

11 Viscometer calibration 15
11.1 Principle 15
11.2 Standards and apparatus 15
11.3 Calibration conditions 16
11.4 Number of measurements 16
11.5 Check for cleanliness and finish 16
11.6 Determining the ball density 17
11.6.1 Ball mass 17
11.6.2 Ball diameter 17
11.6.3 Ball density 17
11.7 Determining the calibration constants 17
11.8 Calibration result 18

12 Measurement uncertainty 18
12.1 General 18
12.2 Measurement uncertainty when measuring viscosity 18
12.3 Measurement uncertainty of the calibration 20

12.3.1 Measurement uncertainty of the calibration constants 20
12.3.2 Measurement uncertainty of the ball density 21

Annex A (informative) Determining measurement uncertainty 22

Bibliography 24

Figures Figure 1 -- Höppler falling-ball viscometer (example of a design) 10

Tables Table 1 -- Symbols and units 6

Table 2 -- Balls for use in falling-ball viscometer having a measurement tube with an inside diameter of 15,94 mm 8

Table 3 -- Minimum fall times 12

Table 4 -- Relative uncertainty of measurement (for coverage factor =) of dynamic viscosity assuming compliance with requirements in Clauses 8 to 10 and for = , as well as fall times t1 as in Table 3 14

Table 5 -- Standard samples for viscometer calibration 15

Table 6 -- Relative variances for calibration at 20 °C and relative uncertainty of measurement (coverage factor =) for the calibration constant (applies for -° °) for calibration as specified in this document 21

Table A.1 -- Multiplication factor F1 as a function of the number of single measurements 23

Table A.2 -- Multiplication factor F2 as a function of the number of single measurements 23