ISO 10111:2019 (E)

Metallic and other inorganic coatings — Measurement of mass per unit area — Review of gravimetric and chemical analysis methods

Contents

Foreword

1 Scope

2 Normative references

3 Terms and definitions

4 Principle

5 Special equipment

6 Preparation of test specimen

- 6.1 Size
- 6.2 Shape
- 6.3 Edge condition
- 6.4 Heat treatment

7 Measurement of coated area

- 7.1 Measurement method
- 7.2 Surface measuring equipment
- 7.2.1 Geometrical (projected) surface area
- 7.2.2 Surface area increase due to roughness (optional)
- 7.3 Number of measurements

8 Determination of mass of coating by chemical analysis

- 8.1 General
- 8.2 Restrictions

9 Gravimetric determination of mass of coating

- 9.1 Specimen size
- 9.2 Limitations
- 9.3 Restrictions
- 9.4 Gravimetric analysis equipment
- 9.5 Procedure
- 9.5.1 General
- 9.5.2 Difference method with dissolution of the coating
- 9.5.3 Direct weighing method with dissolution of the substrate
- 9.5.4 Difference method without dissolution

10 Calculations

- 10.1 Surface density
- 10.2 Thickness

Annex A (informative) Reagents for selective dissolution of metal layers

Page count: 11