ISO 21968:2019 (E)

Non-magnetic metallic coatings on metallic and non-metallic basis materials — Measurement of coating thickness — Phase-sensitive eddy-current method

Contents

Foreword

1 Scope

2 Normative references

3 Terms and definitions

4 Principle of measurement

5 Factors affecting measurement uncertainty

- 5.1 Basic influence of the coating thickness
- 5.2 Electrical properties of the coating
- 5.3 Geometry — Base material thickness
- 5.4 Geometry — Edge effects
- 5.5 Geometry — Surface curvature
- 5.6 Surface roughness
- 5.7 Lift-off effect
- 5.8 Probe pressure
- 5.9 Probe tilt
- 5.10 Temperature effects
- 5.11 Intermediate coatings
- 5.12 External electromagnetic fields

6 Calibration and adjustment of the instrument

- 6.1 General
- 6.2 Thickness reference standards
- 6.3 Methods of adjustment

7 Measurement procedure and evaluation

- 7.1 General
- 7.2 Number of measurements and evaluation

8 Uncertainty of the results

- 8.1 General remarks
- 8.2 Uncertainty of the calibration of the instrument
- 8.3 Stochastic errors
- 8.4 Uncertainties caused by factors summarized in Clause 5
- 8.5 Combined uncertainty, expanded uncertainty and final result

9 Precision

- 9.1 General
- 9.2 Repeatability (r)
- 9.3 Reproducibility limit (R)

10 Test report

Annex A (informative) Eddy-current generation in a metallic conductor

- A.1 General
- A.2 Example 1 — Conductive coating on a non-conductive base material
- A.3 Example 2 — Conductive coating on a conductive and/or magnetic base metal
- A.4 Example 3 — Non-conductive coating on a conductive and/or magnetic base metal

Annex B (informative) Basics of the determination of the uncertainty of a measurement of the used measurement method corresponding to ISO/IEC Guide 98-3

B.1 General
B.2 Type A
B.3 Type B

Annex C (informative) Basic performance requirements for coating thickness gauges based on the phase-sensitive eddy-current method described in this document

C.1 Technical specification
C.2 Check/verification of instruments and probes
C.2.1 Prior to the supply, after repair and at regular intervals after use
C.2.2 Performed on site

Annex D (informative) Examples for the experimental estimation of factors affecting the measurement accuracy

D.1 General
D.2 Edge effect
D.3 Base metal thickness
D.4 Surface curvature
D.5 Conductivity and permeability of the base metal
D.6 Lift-off-height

Annex E (informative) Table of the student factor

Annex F (informative) Example of uncertainty estimation

F.1 Sample details
F.2 Steps

Annex G (informative) Details on precision

G.1 General notes on the interlaboratory test
G.2 Samples
G.3 Thickness gauges
G.4 Calibration
G.5 Number of measurements
G.6 Evaluation

Page count: 39