DIN ISO 15472:2020-05 (E)

Surface chemical analysis - X-ray photoelectron spectrometers - Calibration of energy scales (ISO 15472:2010); Text in English

Contents

Page

Foreword ... iv

Introduction ... v

1 Scope ... 1

2 Normative references ... 1

3 Symbols and abbreviated terms ... 1

4 Outline of method ... 2

5 Procedure for calibrating the energy scale ... 5
5.1 Obtaining the reference samples ... 5
5.2 Mounting the samples ... 6
5.3 Cleaning the samples ... 6
5.4 Choosing the spectrometer settings for which energy calibration is required ... 6
5.5 Operating the instrument ... 6
5.6 Options for initial or subsequent calibration measurements ... 7
5.7 Measurements for the peak binding-energy repeatability standard deviation and the scale linearity ... 7
5.8 Calculating the peak binding-energy repeatability standard deviation ... 8
5.9 Checking the binding-energy scale linearity ... 11
5.10 Procedure for the regular determination of the calibration error ... 12
5.11 Procedures for correction of the instrument binding-energy scale ... 13
5.12 Next calibration ... 15
5.13 Establishing the calibration interval ... 15

Annex A (normative) Least-squares determination of the peak binding energy by a simple computational method ... 16

Annex B (informative) Derivation of uncertainties ... 19

Annex C (informative) Citation of the uncertainties of measured binding energies ... 21

Annex D (informative) Measurements of modified Auger parameters measured using XPS instruments equipped with a monochromated Al X-ray source ... 23

Bibliography ... 26