ISO 23114:2020-01 (E)

Fine ceramics (advanced ceramics, advanced technical ceramics) - Test method for determining bonding strength of ceramic coatings

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Symbols 3

5 Principle 3

6 Apparatus 5
6.1 Testing machine 5
6.2 Data acquisition 5
6.3 Dimension-measuring device 6
6.4 Testing fixture 6

7 Test pieces 7
7.1 Test piece preparation 7
7.1.1 Coating sample 7
7.1.2 Coupling bar 7
7.1.3 Joining of coating sample with coupling bar 7
7.2 Test piece storage 8
7.3 Number of test pieces 8

8 Test procedure 8
8.1 Placement of testing pieces 8
8.2 Test mode and rate 8
8.3 Measurements of the tensile bonding strength 8
8.4 Measurements of the shear bonding strength 9
8.5 Evaluation of the true coating debonded area 9
8.6 Post test 9

9 Calculation of results 10
9.1 Tensile bonding strength of ceramics coating 10
9.2 Shear bonding strength of ceramics coating 10

10 Analysis of precision and uncertainty 10

11 Test report 10

Annex A (informative) Interlaboratory testing 12

Bibliography 13